

Abstract

A process serves to record the deformation of objects (1). In order to facilitate reliable evaluation even in the case of relatively large deformations, during the deformation of the object (1) a sequence or series of images of the object is recorded with a measuring process. The differential between two sequential images is formed. These differentials are integrated (Fig. 1).